

STRUCTURE



The ceiling joists are not secured and are pulling away from the headers. Have a qualified contractor further evaluate and repair to reduce the risk of continued deterioration.